HOUSE OF MANCHESTER

GENERAL NOTE SHEET

IT WAS OBSERVED BY THE TECHNICIAN THAT THE MAKE UP AIR VOLUME DID NOT APPEAR TO SUFFICIENTLY MATCH THE EXHAUST VOLUME IN THE KITCHEN AREA. LACK OF ADEQUATE MAKE UP AIR CAN BE THE CAUSE OF UNDERSIRED NEGATIVE BUILDING PRESSURE. THIS CONDITION CAN LEAD TO SEVERAL COMMON PROBLEMS SUCH AS SEWER ODOR, LACK OF CONSISTENT SPACE TEMPERATURE CONTROL, AND PROBLEMS WITH KITCHEN EQUIPMENT AND WATER HEATER PILOT LIGHTS. WE RECOMMEND INCREASING THE AMOUNT OF MAKE UP AIR BEING PROVIDED TO THE SPACE.



AIR BALANCE SUMMARY

DATE PAGE 10-15-19 3

PROJECT: HOUSE OF MANCHESTER

2256 LOSSEE RD. SUITE E. N. LAS VEGAS, NV. 89030

ROOM	REQ'D. AIR CHANGES PER HOUR	ACTUAL AIR CHANGES PER HOUR	DESIGN CFM			ACTUAL CFM		
			SUPPLY	RETURN	EXHAUST	SUPPLY	RETURN	EXHAUS
KITCHEN	N/A	N/A	NS	NS	3600	1528	-0-	3260
					<u> </u>			
					<u>├</u> ───			
					<u>├</u> ───			
MARKS:					AIR SYSTEM TO F			L

OSHPOD - AD

N

MM-6218

CERTIFIED MEMBER - NATIONAL ENVIRONMENTAL BALANCING BUREAU